

Product Change Notification Number: F02/2011

Date: 2011-09-26

Title: Carrier tape material change in multilayers 0805 size

Reason for Change:


- | | | |
|---|----------------------------------|---|
| <input type="checkbox"/> Production | <input type="checkbox"/> Product | <input checked="" type="checkbox"/> Packaging |
| <input type="checkbox"/> Manufacturing Location | <input type="checkbox"/> Quality | <input type="checkbox"/> Material |
| <input type="checkbox"/> Other | | |

List of Product Subjected to Change:

- MLI series, 0805 size
- MLH series, 0805 size
- MLN series, 0805 size
- MLS series, 0805 size
- MLP series, 0805 size

Change Description: All 0805 multilayers supplied by Ferroxcube will be packaged in paper carrier tape instead of polystyrene carrier tape. Affected dimensions on blister tape compared to old dimensions are shown below:

Dimensions of blister tape



Previous dimensions (in mm)

Type	A	B	T	W	P	F	K
MLI, MLN, MLP, MLS, MLH	1.42	2.25	0.22	8	4	3.5	1.04

Current dimensions (in mm)

Type	A	B	T	W	P	F
MLI, MLN, MLP, MLS	1.5	2.3	0.97	8	4	3.5
MLH	1.58	2.42	0.95	8	4	3.5