

Product Change Notification Number: F04/2013

Date: 2013-11-26

Title: Withdrawal of material 3B8 and replace it by material 3C90.

Reason for Change:

- | | | |
|---|----------------------------------|--|
| <input type="checkbox"/> Production | <input type="checkbox"/> Product | <input type="checkbox"/> Packaging |
| <input type="checkbox"/> Manufacturing Location | <input type="checkbox"/> Quality | <input checked="" type="checkbox"/> Material |
| <input type="checkbox"/> Other | | |

List of Product Subjected to Change:

Description	12NC
P22/13-3B8	432202207971
P26/16-3B8	432202209851
RM10/I-3B8	432202250401
RM10/I-3B8-A160	432202250461
RM10/I-3B8-A250	432202250481
RM10/I-3B8-A400	432202250501
RM14/I-3B8	432202503801
RM14/I-3B8-A250	432202503861
RM6S/I-3B8	432202247851
RM8/I-3B8-A160	432202251471
RM8/I-3B8	433802002341
RM8/I-3B8-A400-E1	434102206411

Change Description: Ferroxcube will discontinue production of 3B8 material. Upgraded alternative material is 3C90. Below is replacement list.

Description	12NC	Replacement	12NC of Replacement	YPN of Replacement
P22/13-3B8	432202207971	P22/13-3C90	432202535061	AG3PP02213003U90PS
P26/16-3B8	432202209851	P26/16-3C90	432202208661	AG3PP02616005U00PS
RM10/I-3B8	432202250401	RM10/I-3C90	432202502201	BG3RMI1000004U90PS
RM10/I-3B8-A160	432202250461	RM10/I-3C90-A160	432202502211	BG3RMI100000B160PS
RM10/I-3B8-A250	432202250481	RM10/I-3C90-A250	432202502221	BG3RMI100000B250PS
RM10/I-3B8-A400	432202250501	RM10/I-3C90-A400	432202502241	BG3RMI100000B400PS
RM14/I-3B8	432202503801	RM14/I-3C90	432202503501	BG3RMI1400007U00PS
RM14/I-3B8-A250	432202503861	RM14/I-3C90-A250	432202503531	BG3RMI140000B250PS
RM6S/I-3B8	432202247851	RM6S/I-3C90	432202247471	BG3RMIS600002U60PS
RM8/I-3B8-A160	432202251471	RM8/I-3C90-A160	432202501811	BG3RMI080000B160PS
RM8/I-3B8	433802002341	RM8/I-3C90	432202501801	BG3RMI0800003U60PS
RM8/I-3B8-A400-E1	434102206411	RM8/I-3C90-A400	432202501841	BG3RMI080000B400PS